DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-005214 Address: 333 Burma Road **Date Inspected:** 14-Jan-2009

City: Oakland, CA 94607

OSM Arrival Time: 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Location: Shanghai, China

CWI Name: CWI Present: Yes Liu Yang / Xu Le Feng No **Inspected CWI report:** Yes **Rod Oven in Use:** Yes No N/A No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes N/A **Delayed / Cancelled:** No

Bridge No: 34-0006 **Component:** TOWER COMPONENTS

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Gady Rao, was present during the times noted above for observations relative to the work being performed.

Bay 10

SAW - FCM - Materials:

SAW welding of weld joint WD1- A 467 - 23M - 3 - 9A, A 467 - 18M - 4 - 10B, A 467 - 18M - 3 - 10B, A 467 - 18M -- 18M - 4 - 9A, A 467 - 18M - 3 - 9B, located on; PCMK P859 - 1 to P 202 - 1. Welder is identified as 201750. ZPMC QC is identified as Wu Ming Kia. The welding variables recorded by QC appeared to comply with the B – T - 4221 - B - U3C - S - 1.

FCAW

- 1) FCAW welding of welds joint NSD1-SA 109 2A located on PCMK SA 109 to P709. Welder is identified as 048378. ZPMC QC is identified as Chen Shou Hua / Liu Yang. The welding variables recorded by QC appeared to comply with the B-T-2231-TC-U5-F.
- 2) FCAW welding of welds joint NSD1-SA 108 1B, 3B located on PCMK SA 108 to P709. Welder is identified as 040345 / 053474. ZPMC QC is identified as Chen Shou Hua / Liu Yang. The welding variables recorded by QC appeared to comply with the B-T-2231-TC-U5-F.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

3) FCAW welding of welds joint NSD1-SA 166 E / F - 20, 21, 25, 26 located on SKIN - A, Lift - 2. Welder is identified as 040533 / 053869 / 040261 / 050041. ZPMC QC is identified as Jin Dong Liang / Liu Yang. The welding variables recorded by QC appeared to comply with the B-T-2332-TC-P5-F.

Doubler plate welding:

- 4) FCAW welding of welds joint NSD1-SA 10 A / K 7, 8 & SA 76 A / H 7, 9 located on P476 to P351 and P 819 to P633. Welder is identified as 040343 / 040261 / 052075. ZPMC QC is identified as Liu Liang / Liu Yang. The welding variables recorded by QC appeared to comply with the B-T-4332-TC-P4-F.
- 5) FCAW welding of welds joint NSD1 SA 76 A / H 18 located on P476 to P351 and P 408 to SA 76. Welder is identified as 054069. ZPMC QC is identified as Liu Liang / Liu Yang. The welding variables recorded by QC appeared to comply with the B-T-2332-TC-P4-F.

BAY 11

SAW - NON-FCM

SAW welding of weld joint WSD1-SA 388 C / D – 4, 21B, 23B, 34 located on; SKIN-C; LIFT-2. Welder is identified as 067993. ZPMC QC is identified as Li Hong Fei / Xu Li Feng. The welding variables recorded by QC appeared to comply with the B-T -2221-B-U3C-S- 2 & B - T - 2321- B - P3 - S - 2.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045., who represents the Office of Structural Materials for your project.

| Inspected By: | Rao, Gady | Quality Assurance Inspector |
|---------------|------------------|-----------------------------|
| Reviewed By: | Clifford,William | QA Reviewer |